

Wayne

STATE OF UTAH
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING
1594 West North Temple - Suite 1210
Box 145801
Salt Lake City, Utah 84114-5801
Telephone: (801) 538-5291
Fax: (801) 359-3940

RECEIVED

DEC 22 2014

DIV. OF OIL, GAS & MINING

LARGE MINING OPERATIONS PROGRESS REPORT

January 1, 2013 to December 31, 2013

The information required in this form is based on provisions of the Mined Land Reclamation Act, Title 40-8, and the R647 rules under the Utah Minerals Regulatory Program. It is due January 31 of each year.

1. Mine Permit Number: M/015/0062
2. Mine Name: ECDC CLAY MINE
3. Name of Operator/Permittee: ECDC ENVIRONMENTAL

Note: If Operator's address, company representative or phone number have changed, please provide a replacement page for the Notice of Intention together with form MR-REV available on the Division's web page at https://fs.ogm.utah.gov/pub/mines/minerals_related/forms/MR-REV.pdf.

4. Report the gross amount of ore mined and waste moved:

Gross Ore Mined 0 Tons, or 0 yd³
Waste Material Moved 0 Tons, or 0 yd³

5. New disturbance created during the year 0 Acres
Area reclaimed during the year 0 Acres
Total disturbed area at the end of the year 0 Acres*

*The total disturbed area should not be greater than the permitted/bonded acreage


6. Briefly describe the reclamation work performed during the past year. (Submit form MR-SITE (https://fs.ogm.utah.gov/pub/mines/minerals_related/forms/MR-SITE.pdf) to apply for full or partial bond/site release). Attach additional sheets if needed.

N/A

7. Include an updated map depicting surface disturbance and reclamation performed during the year (Rule R647-4-105).

I hereby certify the information provided in this report is true and correct to the best of my knowledge and belief.

Name (Typed or Print): DARIN OLSON
Title of Operator: EM
Signature of Operator: Dolson
Date: 9-23-2014




Existing Road Area
Description of Disturbed Boundaries

Beginning at the NW 1/16 Corner of the SW quarter of the NE quarter of Section 1, T16S, R11E, SLBM, thence S00°22'11"E 241.82'; thence N58°56'12"W 279.66'; thence N42°16'06"W 140.23'; thence N27°40'53"W 119.15'; thence N02°32'52"E 192.59'; thence N26°21'10"E 326.47'; thence N46°33'55"E 300.77' to the property line; thence S01°07'29"E along said property line 138.03'; thence S46°14'33"W 197.51'; thence S23°35'47"W 275.32'; thence S02°55'37"W 163.11'; thence S36°50'52"E 142.08'; thence N90°E 181.06' to the Point of Beginning consisting of 3.15 acres more or less.

Existing Mining area
Description of Disturbed Boundaries

Beginning at the NW 1/16 corner of the SW quarter of the NE quarter of Section 1, T16S, R11E, SLBM, thence running S88°42.5'E 1363.56' to the NE 1/16 corner of the SW quarter of the NE quarter of Section 1, thence S00°54.5'E, 1342.77' to the SE 1/16 corner of the SW quarter of the NE quarter of Section 1, thence N9°35'W 521.54', thence N14°03'51"W 604.19', thence N61°26'21"W 150.28', thence N89°00'51"W 228.67', thence N45°03'33"W 517.42', thence N01°47'44"E 342.36' to the point of beginning, containing 29.6 acres more or less.

DRAWN BY:	L. Johnson
CHECKED BY:	
DATE:	October 1, 1999
SCALE:	NTS
JOB NO.:	047
DRAWING NO.:	




Talon Resources

Technical Group

375 South Carbon Ave.
 Price, Utah 84601
 Phone (435) 637-5032 ext 711
 FAX (435) 637-7330

ECDC
 ENVIRONMENTAL
 Clay Mine Site
 Vicinity Map

EXHIBIT
 II





September 23, 2014

Vicky Southwick, Executive Secretary, Mining Program
Department of Natural Resources
Division of Oil, Gas & Mining
1594 West North Temple, Suite 1210
Salt Lake City, Utah 84114-5801

DIV. OF OIL, GAS & MINING

DEC 22 2014

RECEIVED

Subject: ECDC Clay Mine (M/015/062) Annual Report for 2013

Dear Vicky:

As per state rule: R647-4-121, please find enclosed the annual report for the referenced clay mine. Also included is a site vicinity map. The map shows the location of the clay mine.

The mine is currently active; however no mining activity has taken place since summer of 2000. Currently there is approximately 1,000 CY of clay remaining in a stockpile.

No reclamation or disturbance has occurred during the reporting period. If you have any questions or need additional information please call me at 435-888-4115.

Sincerely,

A handwritten signature in black ink, appearing to read "D Olson", with a long horizontal flourish extending to the right.

Darin Olson
ECDC Environmental Manager